

IF THE PAGE FILMED IS NOT
AS LEGIBLE AS THIS LABEL,
IT IS DUE TO THE QUALITY
OF THE ORIGINAL.

Superfund Site Strategy Recommendation

SITE NAME: Denton County Sanitation SITE NUMBER: TXD980750558

ALIAS SITE NAME:

ADDRESS: 1018 Frenchtown Rd.

CITY/COUNTY OR PARISH: Argyle / Denton

STATE: TX ZIP:

RECOMMENDATION:

1. NO FURTHER ACTION PLANNED UNDER SUPERFUND: X
2. FURTHER PRE-REMEDIAL INVESTIGATION ACTION NEEDED UNDER SUPERFUND:

PA:

SSI:

LSI:

OTHER:

TO BE PERFORMED:

PRIORITY: HIGH: MEDIUM:

1. ACTION MAY BE APPROPRIATE UNDER OTHER AUTHORITY:
NPDES: SPCC: 404: TSCA: UIC: RCRA:
SMCRA: STATE: OTHER:

DISCUSSION:

Denton County sanitation was a trash hauling service which collected trash and transported the material to municipal landfills. No waste was generated, stored, transferred, or disposed of at the facility. No Further Remedial Action is indicated under Superfund.

DENTON CNTY SAN
TXD 980750558

Copies to (please list): TRAC, GTC, GW-SP, AISTDR

RECOMMENDED BY: [Signature]

DATE: 08/02/91

SUPERFUND FILE

APPROVED BY: [Signature]

DATE: 5-1-92

DEC 09 1992

REORGANIZED



9458793